




**HM 0+20**  
FN=0.10 FW=1.50




**HM 0+80**  
FN=0.00 FW=2.50




**HM 1+40**  
FN=0.20 FW=1.00




**HM 0+40**  
FN=0.10 FW=1.40




**HM 1+00**  
FN=0.10 FW=1.90




**HM 1+59**  
FN=0.30 FW=0.60



**HM 0+60**  
FN=0.00 FW=2.30



**HM 1+20**  
FN=0.10 FW=1.40



**HM 1+80**  
FN=0.20 FW=0.80

